

CRUCIBLE USER MANUAL

altar

Altar Tech LLC

altervape.com

The Crucible User Manual

This guide provides detailed instructions on using, cleaning, and maintaining your borosilicate quartz terp slurper/banger hybrid.

Overview and Features

The Crucible is a premium borosilicate quartz terp slurper/banger hybrid designed for superior extract vaporization. It features auto-spinning vortex holes and elegant Flower of Life pattern etchings, making it both functional and aesthetically pleasing. Available in 14mm and 10mm male slide sizes, it is intended to be used with "The Orb" as its carb cap.

Key Features:

- **Extra Long Vapor Column:** Reduces heat transfer to the stem and joint, ensuring easy handling and minimizing overspill, which can cause a sticky mess.
- **Extra Thick Bottom:** Increases thermal capacity and heat retention for consistent and efficient vaporization.
- **Vortex Holes:** Create an auto-spinning effect that enhances vapor production and evenness, which can be further enhanced with optional terp pearls.

Usage Instructions

Using The Crucible with Extracts

1. **Optimum Temperature Range:**
 - 500°F - 550°F: Low temperature, flavor saver, lots of terpenes, less vapor.
 - 550°F - 600°F: Medium temperature, good flavor, medium vapor.
 - 600°F - 650°F: High temperature, less flavor, more vapor.
2. **Required Items:**
 - A rig or similar piece of glassware.
 - The Altar
 - The Orb or a carb cap.
 - A dabber.
 - Terp pearls (optional).
3. **Step-by-Step Instructions:**
 - Place The Crucible in the axial coil heater and set the desired temperature.
 - If desired, place terp pearls in The Crucible.
 - Wait until The Crucible is hot (90 seconds to 2 minutes).
 - Carefully pick up The Crucible by the stem near the curve and place it in your rig.
 - Using the dabber, add your extract to The Crucible.
 - Place The Orb on top of The Crucible.
 - Inhale until vapor production ceases or the taste becomes undesirable.

- Clean The Crucible by placing it in an alcohol bath or using cotton swabs dipped in alcohol for added cleaning.
 - Ensure The Crucible is free of all alcohol residue before use.
- 4. Safety Tips:**
- Exercise caution when handling The Crucible and Altar, as they become very hot during use.
 - Always use The Crucible in a well-ventilated area.
 - Handle isopropyl alcohol with care, keeping it away from heat sources, electronics, and other possible ignition sources.
 - Do not leave The Altar on and unattended, treating it like a hot stovetop or lit candle.

Cleaning and Maintenance

1. Cleaning Procedures:

- **Alcohol Bath:**
 - After each use, dunk the hot portion of The Crucible in an alcohol bath.
 - Remove it from the bath before it fully cools and shake off the majority of the residue.
 - The residual heat should evaporate any remaining alcohol. Always ensure The Crucible is alcohol residue-free before placing it back on The Altar to heat.
- **Cotton Swabs:**
 - While The Crucible is still hot, use an included cotton swab to wipe out leftover concentrate.
 - An additional swab dipped in alcohol can be used afterward to remove more residue.

2. Important Cleaning Notes:

- Ensure The Crucible is free of all alcohol residue before heating to prevent any unwanted combustion or residue burning.

By following these instructions, you can enjoy consistent and flavorful vaporization sessions with The Crucible and The Orb. For any troubleshooting needs, refer to The Altar's manual or contact customer support for assistance.